

## Selection and Ordering data

Order No.

### SITRANS LU AO

Provides remote analog output for the measurement points of the SITRANS LU10 level monitor.  
Approvals: CSA<sub>NRTL/C</sub>, FM, CE

C) **7ML5810-1A**

### *Instruction manual*

English

C) **7ML1998-5CE01**

German

C) **7ML1998-5CE31**

Note: Instruction manuals should be ordered as a separate line item on the order.

This device is shipped with the Siemens Milltronics manual CD containing the complete ATEX Quick Start and instruction manual library.

C) Subject to export regulations AL: N, ECCN: EAR99