


Schematics

Circuit diagram and terminal assignment



Insulation monitoring: terminal 4

PTC sensors: terminal 10-11

Shield winding: PE terminal (insulated)

Rated input
voltage
 U_{1N}

V

230

Rated output
voltage
 U_{2N}

V

230
115

Connections and links

Transformer
type

4AT

Primary

U_{1N}

1-2

Secondary

U_{2N}

3-5
4